

**DIRECTIONS:**

Apply diluted or undiluted with foam unit, hand held sprayer or conventional brush to surfaces to be cleaned. Allow some contact time for product to activate the calcium carbonate.
 Heavy Build-up - apply at full strength and allow to sit for 1-3 min. Agitate or brush to remove build-up. Moderate Build-up 1:1 – 3:1 Light Build-up 3:1 Daily cleaning and Polished Aluminum surfaces 3:1 – 10:1 or as desired.
 Rinse or pressure wash off excess concrete remover to neutralize.
****Never apply concrete remover at full strength to a sun baked surface!**

The Worlds strongest concrete remover and equipment wash. Strips down the heaviest concrete build-up. Patented Synthetic acid technology, X-1000 is in a class of its own. High temp stability and zero corrosion rates to metal surfaces and your equipment. Will not affect surface areas or paint of equipment. 100% bio-degradable and environmentally friendly! Classified as a mild skin irritant. Will not freeze! No Solubility limits! Will remove concrete, grease, oil and mineral scale buildup. Product can be used as a daily truck wash to remove built-up concrete without any neutralization. So safe, it can be used on any surface, including glass, aluminum, chrome, rubber, plastic, or paint. Product also includes detergents for degreasing, corrosion inhibitors, optical brighteners, foaming agents, water softeners, and surface expanders.



Safety, Storage, Shelf Life: Always wear proper PPE when handling or working with any chemical. Do NOT apply any chemicals on sun baked surfaces. Product is guaranteed for one year in original container.

X-1000

Acid Replacement Technology

- **WORLD'S STRONGEST CONCRETE REMOVER & EQUIPMENT WASH**
- **100% BIODEGRADABLE** • **NON-CORROSIVE,**
- **NON-REGULATED**



○ 2.5 Gal. ○ 5 Gal. ○ 55 Gal. ○ 275 Gal.

HEALTH HAZARD DATA, EFFECTS OF OVEREXPOSURE, FIRST AID:

Inhalation: No hazards expected. If symptoms occur, remove affected person to fresh air; if breathing has not returned to normal within a few minutes after exposure, get medical attention.

Skin: No hazards expected. If contact occurs, wash affected area with soap and water; remove and launder contaminated clothing before reuse; if irritation occurs, seek medical attention.

Eyes: Remove contact lenses. Immediately flush eyes for 15 minutes in clear running water while holding eyelids open; seek medical attention.

Ingestion: Drink two glasses of water followed by milk, milk of magnesia or other nonalcoholic liquids; DO NOT induce vomiting; seek medical attention.

Carcinogens: Product contains no known carcinogens.

NFPA Rating

0 = Non - Hazardous
 1 = Slight Hazard
 2 = Hazardous
 3 = Extreme hazard
 4 = Deadly

MADE IN ACCORDANCE
 WITH ALL GOVERNMENT
 REGULATIONS



D.O.T. Non-Regulated

In Case of Emergency, Contact:



PATENT #5,672,279



www.KCPE.CA (866) 637-5474